# University of Montana ScholarWorks at University of Montana

Graduate Student Theses, Dissertations, & Professional Papers

Graduate School

2019

# Environmental Site Assessment and Hydrogeologic Impacts to Groundwater at St. Ignatius, Montana and Hanford, Washington

Ryan M. Carter

# Let us know how access to this document benefits you.

Follow this and additional works at: https://scholarworks.umt.edu/etd

Part of the Environmental Indicators and Impact Assessment Commons, Environmental Monitoring Commons, Other Environmental Sciences Commons, and the Water Resource Management Commons

#### Recommended Citation

Carter, Ryan M., "Environmental Site Assessment and Hydrogeologic Impacts to Groundwater at St. Ignatius, Montana and Hanford, Washington" (2019). *Graduate Student Theses, Dissertations, & Professional Papers*. 11381. https://scholarworks.umt.edu/etd/11381

This Professional Paper is brought to you for free and open access by the Graduate School at ScholarWorks at University of Montana. It has been accepted for inclusion in Graduate Student Theses, Dissertations, & Professional Papers by an authorized administrator of ScholarWorks at University of Montana. For more information, please contact scholarworks@mso.umt.edu.

# ENVIRONMENTAL SITE ASSESSMENT AND HYDROGEOLOGIC IMPACTS TO GROUNDWATER AT ST. IGNATIUS, MONTANA AND HANFORD, WASHINGTON

Ву

#### RYAN MCKEE CARTER

Bachelor of Science, Eastern Washington University, Cheney, Washington, 2009

**Professional Portfolio** 

presented in partial fulfillment of the requirements

for the degree of

Master of Science in Environmental Studies

The University of Montana

Missoula, MT

May 2019

Approved by:

Scott Whittenburg, Dean of the Graduate School

Dr. Vicki Watson, Chair Environmental Studies

John P. McDonald, Committee Member Professor Affiliate, Intera, Inc.

# © COPYRIGHT

Ву

Ryan Mckee Carter

2019

All Rights Reserved

Carter, Ryan, M.S., May 2019

Professional Portfolio: Environmental Site Assessment and Hydrogeologic Impacts to Groundwater at St. Ignatius, Montana and Hanford, Washington

Chairperson: Dr. Vicki Watson

The following Environmental Studies Master's Portfolio is a compilation of works completed individually and with peers in order to fulfill requirements for the Master of Science degree. These works demonstrate range, depth, and the interdisciplinary nature of the course of study. As an undergraduate student at Eastern Washington University, I studied Environmental Science with a concentration in hydrogeology. I was interested in learning about the natural world and wanted to develop a deeper connection to it. Inevitably, I was exposed to courses that examined the causes and effects of hazardous waste site remediation, and this topic became my passion. The Environmental Studies program has provided an opportunity to shift my focus from deepening my understanding of the questions about how and why hazardous waste is regulated and disposed of, to advancing my knowledge of what should come next. I have focused my efforts on environmental remediation and how people can respond to environmental issues such as hazardous waste disposal. The following describes the interdisciplinary works contained in this portfolio, the skills and learned outcomes achieved, and how the individual projects, papers, and reports connect coherently.

The first chapter, titled "An Environmental Site Assessment, St, Ignatius, Montana", is a Phase I commercial property environmental site assessment (ESA) report, completed on behalf of Pioneer Technical Services, Missoula, Montana (Carter, 2011). The chapter describes the purpose of the environmental assessment, limiting factors, site conditions, and results of visual observations at the site, findings, and conclusions. The entire report is included in this portfolio paper verbatim with minor edits for clarity. Research was focused on whether the property development had affected the local environment. This report touched on many of my academic interests including policy research, property development, and externalities impacting human and environmental health. This report was the first site assessment and characterization I completed since beginning my professional work in the environmental arena.

In the next chapter titled "Hydrogeology Characteristics of a Waste Management Area, Hanford, Washington", I researched the local geologic and hydrologic properties underneath a waste repository (waste tanks) used for historic nuclear processing waste storage. This chapter contains the hydrogeology section from a larger report (Sulloway, et al., 2018) with minor edits for clarity, written by a team of authors, including myself, by CH2M Hill Plateau Remediation Company (CHPRC), specifically by the Soil & Groundwater Remediation Group (S&GRP). This individual chapter reflects an early remediation site characterization regulated by the state of Washington.

The final chapter titled "Hydrogeologic factors of a Chromium Plume at Hanford, Washington" consists of the hydrologic testing done to delineate the operable units chromium plume (Rohay and Carter, 2018). The chapter presented here is verbatim with minor edits for clarity. In this

paper I researched, examined and quantified the hydrogeology of a chromium plume based on the results of drilling, sampling, and characterizing the plume. During 2016 and 2017, 11 wells were drilled and sampled to characterize the nature and extent of the southeast chromium plume. Based on groundwater sample results from these new wells, the southeast chromium plume extends further than the extent based on data available in 2015. This individual chapter shows an example of a recent site characterization used for a future remediation project to clean the contaminants within the aquifer and is part of a larger report.

This portfolio highlights some of the products that resulted from the diverse work and practical experience gained throughout my career. I have departed my formal training at this university with a solid understanding of complex earth systems and environmental issues—and the tools and expertise necessary to work to mitigate and adapt to their effects.

# **Acknowledgements**

The completion of this project is due to the efforts of many people that gave their time to help advance the work of these site assessments. I want to thank:

To my advising professor, Dr. Vicki Watson, thank you for your constant support when it was needed. You showed trust in me to complete this project and degree. Thank you for all the work you've dedicate to your students.

To the Chair of the Environmental Studies Program, Dr. Phil Condon, thank you for providing your feedback and support as I made my way through each step of this professional portfolio process.

To John McDonald and the other mentors over the years, Chuck Miller and Todd Lorenzen, thank you for including me in the work you do and supporting my needs in these projects and the many others. To Travis Hammond, Bill Faught, Jessica Ni, Heather Sulloway, and Virginia Rohay, and all the other contributors to the full reports in chapters 2 and 3. Thank you to Margo Aye for the graphics and figures throughout chapters 2 and 3.

To my wonderful family: Leslie, Caden, Lincoln, Averie, Aaron, and Aile, you have all offered me so much support and love throughout our time together. Thank you to my parents and siblings, Dan, Janean, Carleen, Janae, Raelene, Kendra, Kerianne, Karissa, and Brent. All my love and appreciation.

# **TABLE OF CONTENTS**

Chapter	1: Environmental Site Assessment, St. Ignatius, Montana	1
1.1	INTRODUCTION	2
1.2	SITE DESCRIPTION.	6
1.3	RECORDS REVIEW	13
1.4	SITE RECONNAISSANCE	19
1.5	INTERVIEWS	23
1.6	FINDINGS/CONCLUSIONS	23
1.7	REFERENCES	24
Chapter	2: Hydrogeology Characteristics of Waste Management Area U, Hanford, Washington	26
2.1	INTRODUCTION	27
2.2	STRATIGRAPHY	28
2.3	HYDROGEOLOGY	31
2.4	GROUNDWATER FLOW SYSTEM	34
2.5	VADOSE ZONE	40
2.6	SOIL MOISTURE FACTORS	40
2.7	HYDROGEOLOGIC CONSIDERATIONS	42
2.8	GROUNDWATER CHEMISTRY	42
2.9	SUMMARY OF VERTICAL DISTRIBUTION	44
2.10	REFERENCES	47
Chapter	3: Hydrogeologic Factors of a Chromium Plume at Hanford, Washington	49
3.1	INTRODUCTION	50
3.1	SAMPLING AND ANALYSIS PLAN REQUIREMENTS	50
3.2	CONTAMINANTS OF CONCERN	53
3.3	CHARACTERIZATION WELLS	55
3.4	GROUNDWATER SAMPLES	56
3.5	VERTICAL PROFILE SAMPLING	57
3.6	GROUNDWATER DATA	57
3.7	SAMPLING DURING WELL DEVELOPMENT	58
3.8	REFERENCES	59
Chanter	4. Enilogue – Lessons Learned and Future Plans	61

# Figures and Table

Figure 1. Location Map of the St. Ignatius ESA Area	4
Figure 2. View Looking Northeast to the Main Buildings Fronting Highway 93	7
Figure 3. Topographic Map of the St. Ignatius Region	8
Figure 4. Views of the Paved Asphalt Parking Lot and Concrete Pad with Staining	12
Figure 5. Property Remediation Sites Within 0.5 and 1.0 Miles of Subject Property	15
Figure 6. View to the North of the Power-line Transformers	17
Figure 7. Location of Wells Within 0.5 and 1.0 Miles from Subject Property	20
Figure 8. Location Map for the Waste Management Area U	27
Figure 9. General Stratigraphy at the Hanford Site	30
Figure 10. East to West Cross-Section for Waste Management Area U	32
Figure 11. Waste Site Locations Near Waste Management Area U	34
Figure 12. 2015 Water Table Map for the Waste Management Area U	35
Figure 13. Water Elevation Contours in June 2012 Prior to Startup of the 200 West P&T	36
Figure 14. Vertical Contamination Distribution in Well 299-W18-260	43
Figure 15. Locations of the Eleven Southeast Chromium Plume Remedial Design Investigation Wells	52
Table 1. 200-UP-1 Operable Unit Southeast Chromium Plume Depth Discrete Samples	49

#### **Abbreviations**

AMSL above mean sea level

ASL above sea level

ASTM American Society for Testing and Materials

CCU Cold Creek Unit

CERCLA Comprehensive Environmental Response, Compensation and Liability Act

CERCLIS Comprehensive Environmental Response

CFR Code of Federal Regulations

CHPRC CH2M Hill Plateau Remediation Company

COC Contaminant of Concern

DEQ Department of Environmental Quality

DQO data quality objective

EPA Environmental Protection Agency

ERNS Emergency Response Notification System

ESA Environmental Site Assessment

GWIC Ground-Water Information Center

LUST Leaking Underground Storage Tank

MBMG Montana Bureau of Mines and Geology

MWCB DEQ Mine Waste Cleanup Bureau

NPL National Priorities List

P & T Pump and treat

PCB polychlorinated biphenyl

PNNL Pacific Northwest National Laboratory
PTRCF Petroleum Tank Release Cleanup Fund
RCRA Resource Conservation and Recovery Act

SAP Sample and Analysis Plan

S&GRP Soil and Groundwater Remediation Group

SST Single-shell tank

USGS U.S. Geological Survey

UST Underground Storage Tank

WMA Waste Management Area

# Chapter 1: Environmental Site Assessment, St. Ignatius, Montana

#### 1.1 INTRODUCTION

Pioneer Technical Services, Inc. (Pioneer) has conducted a Phase I ESA of the subject property, Estate of Douglas Lloyd Allard Commercial Property, located at 77529, 77547, 77565, and 77579 U.S. Highway 93, St. Ignatius, Montana, 59865 (Carter, 2011). The following Phase I ESA report has been prepared on behalf of Farmers State Bank to document the environmental status of the subject property, which was for sale.

In defining a standard of good commercial and customary practice for conducting an environmental assessment of a parcel of property, the goal of the processes established by this practice is to identify recognized environmental conditions (CERCLA 42 U.S.C. §9601(35) (B)). The term recognized environmental conditions means "the presence or likely presence of any hazardous substances or petroleum products on a property under conditions that indicate an existing release, a past release, or a material threat of a release of any hazardous substances or petroleum products into structures on the property or into the ground, groundwater, or surface water of the property." This Phase I Environmental Site Assessment (ESA) was conducted to determine if, and/or to what extent, hazardous substances or petroleum products were released on the subject property.

The subject property is located in the southwest one-quarter, northeast one-quarter (SW% NE%) of Section 14, Township 18 North (T18N), Range 20 West (R20W) in Lake County, Montana. The subject property is comprised of three real property parcels; two of the parcels are located outside the city limits of St. Ignatius, and one parcel is within the city limits. The cumulative 4.15-acre property includes a gas station, motel, convenience/general store, museum, trading post/gift shop, office building, and restaurant.

Based on site reconnaissance, review of aerial photographs, and review of state and federal environmental databases, it is the opinion of Pioneer that no visibly apparent potential environmental concerns exist at the subject property.

# **SCOPE OF SERVICES**

Pioneer mobilized the necessary equipment and personnel to the subject property located in St. Ignatius, Montana, for the purpose of conducting a Phase I ESA (Figure 1). The site assessment included the following scope of work:

- Interviews with present and past owners/occupants (if available);
- Thorough visual inspection of the property;
- Review of aerial photographs;
- Review of applicable regulatory lists and state and federal environmental databases;
- No samples collected due to the limitations of Phase I ESA requirements (samples are taken for Phase II ESA's)
- Photo documentation of the property; and
- Review of adjoining properties and their uses.




Figure 1. Location Map of the St. Ignatius ESA Area

### **SIGNIFICANT ASSUMPTIONS**

The following information and assumptions are based upon ASTM Standard E 1527-05, Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process (ASTM, 2005). As indicated in ASTM Standard E 1527-05, no environmental assessment can wholly eliminate uncertainty regarding the potential for problematic environmental conditions in connection with a property. This practice is intended to reduce, but not eliminate, uncertainty regarding the potential for recognized environmental conditions in connection with a property and recognizes reasonable limits of time and cost. Additionally, it should be noted that portions of this report are based on unverified information supplied to Pioneer by third-party sources. While efforts have been made to substantiate third-party information, Pioneer cannot guarantee its completeness or accuracy.

Pioneer has performed all activities, appropriate and necessary, to evaluate the environmental status of the property under Phase I ESA guidelines.

### LIMITATIONS AND EXCEPTIONS

This Phase I ESA was conducted in accordance with current industry standards and practices. Pioneer conducted this Phase I ESA specifically for the use of H&E Equipment Services. Any reliance on this report by another party other than those listed on the cover page of this report shall be at such party's sole risk. Some of the work completed by Pioneer included review of information provided by others; therefore, Pioneer assumes no responsibility for conditions not revealed or observed during the Phase I ESA or for conditions not generally recognized as environmentally unacceptable at the time this report was prepared. The information, conclusions, and recommendations provided herein apply only to the property, as it existed during Pioneer's investigation. Should site use or conditions change, the information, conclusions, and recommendations contained herein may no longer apply.

This Phase I ESA did not include a title search for the property.

### **RELIANCE**

This report shall be for the sole benefit of Farmers State Bank and may not be relied upon by any other person or entity without the written authorization of Farmers State Bank.

Parties who seek to rely upon Phase I ESA reports dated more than 180 days prior to the date of reliance do so at their own risk. This limitation in reliance is based on the potential for physical changes at the site, changes in circumstances, technological and professional advances, and guidance related to the continued viability of Environmental Assessment reports, user's responsibilities, and requirements for updating of components of the inquiry as stated in the ASTM Standard E 1527-05.

#### 1.2 SITE DESCRIPTION

The subject property consists of five buildings over three neighboring parcels (Figure 2). The museum/trading post was built in 1974, the general store in 1976, the motel in 1981, the office building in 1985, the Huckleberry Jam Factory in 1990, and the White Buffalo Restaurant in 2002 (Montana Cadastral System). The buildings and a paved parking lot are accessed from a driveway turnoff from Montana's Highway 93. The buildings are oriented with the fronts facing southeast, with the restaurant facing southwest. The northwest border of the property is fenced with a post and wire fence. The property is connected to community water and sanitary sewer service.

### LOCATION AND LEGAL DESCRIPTION

The subject property is located in the SW¼ NE¾ of Section 14, T18N, R20W at an elevation of approximately 2,905 feet above mean sea level (amsl). Information about the property was obtained from the Montana Cadastral Mapping system (gis.mt.gov) and is listed on the Property Record Card in Appendix B. The property area is 180,774 square feet (4.15 acres), of which 18,178 square feet is paved with asphalt, 1,825 square feet is paved with concrete, and 27,442 square feet is orchard. The buildings have a listed first-floor combined area of 15,016 square feet. The street addresses of the subject properties are 77529, 77547, 77565, and 77579 U.S. Highway 93, St. Ignatius, Montana.



Figure 2. View Looking Northeast to the Main Buildings Fronting Highway 93

# SITE AND VICINITY CHARACTERISTICS

The subject property is located off Highway 93, adjacent to the town of St. Ignatius, Montana (Figure 1). Natural topography of the area is generally flat to gently sloping downhill to the northwest, as shown on the topographic map in Figure 3. The subject property has been graded to a level surface and is paved with asphalt, concrete or graveled throughout. The main parking area is located on the southeast side of the five buildings fronting Highway 93 (Figure 1).




Figure 3. Topographic Map of the St. Ignatius Region

# Fixtures within the three parcels include:

- two gas pumps with a two post gas station canopy,
- two large capacity refrigeration units one attached and one detached,
- two concrete vault covers for septic tank access,
- three plastic capped well monitoring access (6" diameter),
- two iron capped well access (6" diameter),
- three hand-pump water spouts,
- one abandoned above-ground sprinkler head,
- six electrical power posts, of which, three have transformers,
- three above-ground propane storage tanks,
- one gas station price sign,
- one gasoline refill port,
- two capped well vents (4" diameter),
- two gated culverts north and southeast storm water drainage areas,
- two ungated/open culverts north and southeast storm water drainage areas,
- and a temporary fireworks stand, removed as of July 24, 2013.

The northern portion of the subject property consists of a mature fruit orchard (Figure 1), approximately half an acre. The subject property is bound on the west by a wastewater treatment pond; and a grass field to the north, approximately ten acres, owned by the city of St. Ignatius (Figure 1). The southwest is bound by a dirt access road to the treatment facility, and by Highway 93 to the east.

The subject property is no longer using the in-place septic system but is connected to municipal sewer. According to the Montana Cadastral, and confirmed with Ms. Linda Chard of the Lake County Environmental Health office, there is no septic permit currently on record for the subject property. Two concrete access covers are in-place over the septic vault. Two domestic water wells were drilled in 1974 and 1978, to depths of 80 and 90 feet, respectively. The subject property is currently connected to municipal water.

There are two refrigeration units, one detached and adjacent to the northwest corner of the restaurant, and one attached at the back of the Huckleberry Jam Factory. At the back of the general store there is a one-quarter inch pvc pipe extended approximately 6 inches from the addition attached to the main building. This pvc pipe is dripping, approximately one drop every 30 seconds, presumed to be water, from a refrigeration unit condenser in the rear of the store. It is assumed that all three of the refrigeration units are still running, due to the vibration and low hum coming from each of the units.

The parking lot appears to be in good condition, without any major cracks or potholes. Approximately 3,000 sq ft is asphalt, 250 sq ft is concrete, and 2,500 sq ft is gravel parking and drive-through. The restaurant parcel's parking area is completely graveled. According to satellite photos elevation records on Google Earth, the elevation on the north end is 2,907 feet asl (above sea level). There is a gentle downslope to the south parking area at the motel, which is at 2,903 feet asl.

There are two open storage areas, accessible from the backside of the museum, and between the museum and trading post. The material stored appears to be interior fixtures, signage and storage bins. There are multiple wire racks/display cases behind the trading post. There is a fenced yard maintenance area behind the general store with no visible fertilizers or pesticides. The three storage areas noted above appears to be an addition to, and run the length of, the back of the general store and museum. The portion behind the general store has metal siding. The portion behind the museum has wood siding.

Equipment on the property includes a pvc frame of a car parking cover, a garbage dumpster, three garbage barrels (partially full with common garbage), one FedEx drop box, various storage racks, empty food service storage buckets, two tractor tires (used as drive-way boundary markers), ladder, and patio furniture. There is an unused, torn bag of wall and ceiling texture left on the concrete step, behind the trading post.

The gas station has two registered 10,000 gallon underground storage tanks (UST's) for unleaded gasoline. These two tanks replaced two previous underground storage tanks, in 2005.

All four tanks are documented in the online Underground Storage Tank Summary Report (Montana DEQ UST Site).

According to property title searches and the ASTM Questionnaire, completed by Ms. Jeanine Allard, Mr. Doug Allard owned and operated the subject properties for 40 years, the earliest structure built in 1974. The property operations ceased in 2011.

# **SITE HISTORY**

The ASTM Standard requires identification of all obvious uses of the property from the present back to the property's first developed use, or back to 1940, whichever is earlier. No evidence was found that the subject property was ever developed for residential or industrial use prior to 1990, as viewed from aerial photos or from the property record search since 1974, from when the earliest structures were built. No evidence of mining activity was found on the site during the site reconnaissance. No evidence of trash dumping or waste burial was noted on the site.

The seven buildings on the subject property parcels were constructed in multiple stages. According to the Property Record Cards, the Flathead Indian Museum and Doug Allard's Trading Post were built in 1974; the General Store was built in 1979; the Lodgepole Motel was built in 1981; the detached office building was built in 1985; the Huckleberry Jam Factory was built in 1990; and the White Buffalo Restaurant was built in 2002 (Figure 2). Pioneer personnel researched the history of the site using the Lake County Tax Records, written reports in the Missoulian newspaper (Sept. 2009), and the written questionnaire completed by Ms. Jeannie Allard. The buildings and property have been vacant since 2011.

### CURRENT USE OF THE PROPERTY

The subject property buildings are no longer used as intended. There are no disposed batteries, barrels or buckets visible on the property. There is minor staining at various locations on the asphalt parking lot indicating spills of oil or other products in isolated areas (Figure 4). The stains appear to be typical for the type of activity on the property and does not appear to pose a threat to the environment.

# DESCRIPTION OF STRUCTURES, ROADS, AND IMPROVEMENTS

The structures on the subject property consist of wood framed and log buildings. The buildings are slab-on-grade. Property records indicate that the buildings have an aggregate first-floor area of 10,396 square feet. The trading post and restaurant have a second floor. The motel, general store, Jam Factory and restaurant have sheet-metal roofing; the museum and trading post have wood shingle roof material.



Figure 4. Views of the Paved Asphalt Parking Lot and Concrete Pad with Staining

## **CURRENT USE OF ADJOINING PROPERTIES**

The subject property is bound on the south-southeast by U.S. Highway 93, two driveways off the highway allow access to the subject property. The adjoining property on the north-northeast is an open grass field/pasture owned by the U.S. government in trust to the local Salish Kootenai Tribe. Agricultural rows were observed on the upper-most slope, some 50 m north of the property boundary (Figure 1).

The property to the north-northwest serves as an aerated wastewater treatment pond, owned and operated by the City of St. Ignatius. The wastewater treatment plant system is a single-cell facultative lagoon that was constructed in 1956, to which five aerators were added in 1989. The lagoon discharges to Matt Creek to the north, which flows part of the year. During periods when Matt Creek flows, the discharge eventually reaches Mission Creek. The system had a history of violations of the National Pollutant Discharge Elimination System discharge permit that include exceeding limits for biochemical oxygen demand, total suspended solids, and fecal

coliform. The discharge has also failed in the past to meet the Confederated Salish and Kootenai Tribes' in-stream water quality standard for ammonia. Because of these past deficiencies, the Salish-Kootenai Housing was granted funding and built a double lagoon wastewater treatment facility south of Mission Creek. This facility services the population south of Mission Creek and the St. Ignatius wastewater treatment plant services the population north of Mission Creek.

The south-southwest boundary is a dirt access road to the wastewater treatment plant. Beyond the road is open grassland, owned, in trust, to the Salish-Kootenai Tribe.

#### 1.3 RECORDS REVIEW

# STANDARD ENVIRONMENTAL RECORD SOURCES

Pioneer reviewed current information from the Federal Superfund Site System (U.S. Environmental Protection Agency [EPA] Superfund System), Comprehensive Environmental Response (CERCLIS) (EPA CERCLIS Search), National Priorities List (NPL) (EPA National Priorities List), Resource Conservation and Recovery Act (RCRA) (EPA RCRA Site), Emergency Response Notification System (ERNS) list (EPA National Response Site), State Equivalent NPL (Montana Department of Environmental Quality [DEQ] NPL), State Equivalent CERCLIS (DEQ CERCLIS), State landfill (DEQ Solid Waste), State and tribal Brownfields Sites (DEQ Brownfields), Underground Storage Tank (UST) site lists (DEQ UST Site), Leaking Underground Storage Tank (LUST) site lists (DEQ LUST Site), and the DEQ Mine Waste Cleanup Bureau (MWCB) (DEQ Mine Waste Cleanup Site).

Pioneer used DEQ and EPA lists to determine if there are any current federal, state, and local government environmental investigations near the site. Pioneer researched DEQ and EPA databases to verify the locations of any current federal, state, and local government environmental investigations that were being conducted within a 0.5 and 1.0 mile radius around the property. Sites found in the various databases, located within 0.5 to 1.0 miles around the property, are shown in Figure 5.

The NPL is a Federal list created by the EPA, which ranks those sites requiring cleanup of hazardous substances as defined under the CERCLA, also known as Superfund. These sites are ranked according to the criteria established by the EPA and are listed in the Code of Federal Regulations (CFR). The EPA updates the NPL periodically. Potential new NPL sites are listed by the EPA in the Federal Register. The NPL was reviewed for sites of concern in the St. Ignatius vicinity by using the Montana NPL listings obtained from the DEQ and EPA databases.

The CERCLIS lists those sites which: 1) have received, generated, transported, or disposed of hazardous wastes prior to November 1980; or 2) have hazardous wastes that have been released to the environment. Inclusion on this list is not itself a judgment about the activities of a site's owners or operators. It does identify sites that may require further investigation because they could pose environmental or public health risks. The CERCLIS is used to track potentially uncontrolled hazardous materials/waste sites. The EPA database shows no CERCLIS sites in Lake County. There are no NPL superfund sites in Lake County.




Figure 5. Property Remediation Sites Within 0.5 and 1.0 Miles of Subject Property

The Montana non-NPL site list was reviewed for sites in Lake County. These non-NPL sites are uncontrolled hazardous substances sites that did not rank high enough to be placed on the NPL list; therefore, they were placed on the Montana DEQ Comprehensive Environmental Cleanup and Responsibility Act (CECRA) Priority Site List. There are four sites listed for Lake County, each listed as inactive landfills (Montana DEQ CECRA Priority List). The CECRA site closest to the subject property is Midway Store Dump site in Ravalli approximately 6 miles southwest, which is located in Section 16, R20W, T17N. The groundwater flow below this dump site is downgradient of the subject property (LaFave et al., 2004).

Pioneer also reviewed the RCRA status of the property with regards to the generation of hazardous wastes on or in the proximity to the property (Appendix D). The subject property is not the site of a registered generator. This indicates that no known disposal activities, spills and/or remediation activities have taken place on the subject property. Review of the database shows that there are 37 registered RCRA handlers in Lake County.

Pioneer reviewed the ERNS list, which is EPA's list of reported CERCLA hazardous substance releases or spills in quantities greater than the reportable quantity, as maintained by the National Response Center. Pioneer's review of the list found no environmental recognized conditions at the subject property or within a 0.5-mile radius of the subject property.

Pioneer reviewed the UST status of the property using a UST registration list, active as of September 2011, provided by the DEQ. The database shows 37 active UST sites, one of which is located within 0.5 miles of the subject property at 240 Mountain View Drive. Review of the UST registration list indicates there has been USTs and/or piping registered at the subject property. The UST Summary Report from September 26, 2011 shows two tanks installed in 1983 and replaced in 2005, which currently have an 'in use' status.

Pioneer reviewed the DEQ LUST site list. There are 37 active LUST sites listed in Lake County. Two of the LUST sites are located within the 1.0-mile radius of the subject property (Figure 5). The closest is an active LUST site at 240 Mountain View Drive at Stuart's Service Center that was resolved in 1995 by removing the contaminated soil to a regulated landfill site outside of the county.

Pioneer reviewed a list of state and tribal Brownfields sites in Montana. Neither the subject property nor any adjoining properties are listed on the targeted Brownfields Assessment Sites list.

Pioneer reviewed MWCB Priority Site List and the Prioritized List of Abandoned Mine Lands (AML) Sites as listed on the DEQ's Online Query system. The DEQ Abandoned Mine Quarry System lists four abandoned hardrock mine sites in Lake County. None of the sites lie within the 1.0-mile radius of the subject property.

## **LOCAL CONTACTS**

The Phase I ESA process can include telephone contacts to local officials. With the availability of environmental records online, this step in the process has become less critical. Since the subject property has always been used for the original purpose since the time it was built, this ESA relies on government records of contamination sites.

The electrical power to the site is supplied by a power pole located north of the White Buffalo Restaurant. There are six power poles on the subject property, three of which have transformers (Figure 6), and were observed to be modern transformers that Pioneer personnel did not suspect of containing PCBs (post-1977 construction of power lines). Pioneer did not contact Northwestern Energy to verify that the transformers do not contain PCBs.




Figure 6. View to the North of the Power-line Transformers

### **EVALUATION OF GROUNDWATER CONDITIONS**

Groundwater flow beneath the city of St. Ignatius is to the northwest (LaFave et al., 2004), however, no site-specific groundwater work was conducted at the subject project. Information about local groundwater conditions was taken from well logs for local groundwater wells that are registered in the State of Montana. The well information was obtained from the Montana Bureau of Mines and Geology (MBMG) Ground-Water Information Center (GWIC) website. Wells within the GWIC system that are within 0.5 to 1.0 mile of the subject property are shown on Figure 7. The two on-site wells closest to the subject property have been used to provide more specific information on depth-to-groundwater and aquifer characteristics near the subject property. The GWIC well location data are provided on a section, quarter-quarter system; therefore, well location data obtained from GWIC should be regarded as approximate.

Wells within the GWIC system that are located on the subject property and in the SW¼ of the NE¼ of S14, T18N R20W are shown in Figure 7. There are two wells located on the subject property, completed in 1974 and 1978. The logs for the wells within the subject property indicate that the subsurface generally consists of clay and gravel to a depth of approximately 90

feet below ground surface (bgs). Static water levels in the nearby wells are 30 to 33 feet below ground surface. The subject property is located above the shallow Post Creek Aquifer (LaFave et al., 2004).

## PHYSICAL SETTING INFORMATION

Information used in determination of the physical setting includes the following:

- On-site reconnaissance by Mr. Ryan Carter of Pioneer on June 26, 2013.
- Aerial photographs (USGS, Microsoft Corp., Bing). A satellite photograph of the area with the property boundary outline is included as Figure 1.
- Montana Cadastral Mapping database, www.gis.mt.gov.

#### HISTORICAL USE INFORMATION

Historical information on the subject property was obtained verbally from the realtor, Mr. Bill McQuirk, representing the Allard Estate and written from the questionnaire from Ms. Jeanine Allard (owner's daughter). Doug Allard has owned and operated the businesses within the subject property since each of the structures were built.

#### 1.4 SITE RECONNAISSANCE

Pioneer conducted the initial Phase I ESA site tour on June 26, 2013. The subject property was vacant except for a temporary fireworks stand on-site. A second site visit on July 24, 2013 to complete a review of the site; the temporary fireworks stand had been removed. During the initial site reconnaissance, Pioneer completed the user portion of the ASTM (E-1528-06) questionnaire (ASTM, 2006). Ms. Jeanine Allard completed the occupant portion of the ASTM (E-1528-06) questionnaire on June 28, 2013.

#### **PROPERTY OBSERVATIONS**

The subject property consists of a gas station, motel, general store, museum, office building, and restaurant. The property observations are limited to the outdoor space and items within the building that could potentially impact the environment. A counter-clockwise inspection of the property was made on foot.




Figure 7. Location of Wells Within 0.5 and 1.0 Miles from Subject Property

The restaurant is a freestanding, two-story log structure with a concrete foundation basement. There is a precast-concrete covered front porch entrance and an attached poured concrete patio on the east of the building. The surrounding parking area is gravel. There were no visible pumps or wells in the immediate vicinity of the building. The detached refrigeration unit, on the northwest corner of the building did not appear to have any leaks or structural damage. The unit is on a concrete slab. A visual inspection of the interior was made from the front door windows. Counters, display cases, chairs, and tables were present, common for restaurant furniture and fixtures.

The Huckleberry Jam Factory is freestanding, single-story, wood-framed, slab on-grade building with a covered front porch area. At the east corner of the building is a capped well access, and two registered above ground storage tanks to the northeast of the building. At the back of the building is a capped iron well, with a 'Campbell' imprint and buried to the top of the cap, partially covered with gravel. The asphalt parking area, in the front of the building has very few oil-based stains, commonly associated with the type of activity for a parking lot. The northeast and northwest, backside area of the building is a graveled drive-through/parking area. There were no visible stains in this area. The refrigeration unit attached at the back of the building appears to be in working condition and had no associated leaks. There are no visible irrigation or sprinkler systems for the associated orchard to the northwest of the Huckleberry Jam Factory. There was no visual inspection of the interior due to no windows or access to the inside of the building.

The Trading Post is an attached, two-story, wood-framed building with a covered front porch entrance. There is a hand pump, water well spigot at the east corner of the building. The asphalt parking area, in the front of the building has very few oil-based stains, commonly associated with the type of activity for a parking lot. The northeast and northwest, backside of the building is a graveled drive-through and parking area. There are no visible signs of any stains in this area. A limited inspection of the interior was made through the windows at the front of the building. Common fixtures, such as counters, display cases and racks, and an upper-balcony area was visible. There is a registered above ground propane tank and a second hand pump, water well spigot at the backside of the building.

The office building is a detached, single-story, concrete foundation with crawl space, log framed building. The office building is behind the trading post and is surrounded by landscaped grass. The small building is empty in the interior and has no visible environmental concerns.

The Flathead Indian Museum is an attached, single-story, wood-framed building with exterior restroom access. The front asphalt parking area has very few oil-based stains, commonly associated with the type of activity for a parking lot. The backside of the museum has an attached storage area with no visible containers that would pose an environmental concern.

The General Store is an attached, single-story, wood-framed building with a covered, wood-floor front porch entrance. The front asphalt parking area has very few oil-based stains, commonly associated with the type of activity for a parking lot. The backside of the general store has an attached storage area with a yard maintenance area with no visible containers of pesticides or toxic substances that would pose an environmental concern.

The gas station, associated with the General Store, has two pumps stations with a two-post metal canopy. The refill ports are on the northwest and southeast sides of the pumps. According to the Montana Department of Environmental Quality's (MDEQ) Petroleum Tank Release Cleanup Fund (PTRCF) Claims & Reimbursement Report, and verified with MDEQ's Ms. Janet Adolf of the Compensation Board, there was petroleum contaminated soil documented when the two registered 10,000 gallon underground storage tanks were being removed, and replaced with two similar 10,000 gallon tanks. Because of the petroleum release, the owner applied to the PTRCF for financial assistance, for reimbursement for the corrective action costs to the operator and/or their environmental consultants and subcontractors. The clean-up was accepted by the MDEQ and the case closed, ratified as of April 21, 2007 and resolved as of July 9, 2008. The registered underground tanks are not currently on the active LUST list.

The Lodgepole Motel is an attached, single-story, wood and log-framed building with seven units. The motel consists of two similar-type buildings, forming an "L" at the south end of the subject property. The front asphalt parking area has very few oil-based stains, commonly associated with the type of activity for a parking lot. The backsides of both motel buildings are grass with what appears to be a storage shed between the two buildings. It is unknown what is

stored inside the shed; there was no inspection of the interior – an internal inspection is recommended. The abandoned septic vault is on the west corner of the two motel buildings. The exposed vault has two covers, one slightly offset, but was not opened during the site visit. Several units have the window shades drawn and the interiors are visible. Common motel fixtures are visible: chairs, nightstands, beds, and storage cabinets. There were no visible environmental concerns.

## PHYSICAL SETTING ANALYSIS

The subject property is a commercial property and is located in a rural-commercial development area. The site is level, and much of it has been paved with asphalt. The site is situated over the shallow Post Creek Aquifer, making protection of groundwater in this area critical. No evidence was observed at the site indicating that petroleum products or other contaminants had been disposed or spilled in a way that would threaten groundwater quality. The site is equipped with a storm drain system to the north and southeast of the property, along Highway 93. The site is served by city water and sanitary sewer.

#### 1.5 INTERVIEWS

Interviews were conducted in accordance with ASTM standards as described in ASTM

Designation E1528-06 (Standard Practice for Limited Environmental Due Diligence: *Transaction Screen Process*) (ASTM, 2006). The current representative of the owner interview was conducted by Mr. Carter via telephone.

#### 1.6 FINDINGS/CONCLUSIONS

Pioneer has performed a Phase I ESA, in conformance with the scope and limitations of ASTM Practice E 1527-05, of the subject property at 77529, 77547, 77565, and 77579 U.S. Highway 93, St. Ignatius, Montana. Any exceptions to or deletions from this practice are described in Sections 1.2 and 1.3 of this report. Based on the findings of this Phase I ESA, it is the opinion of Pioneer that no visibly apparent potential environmental concerns exist at the subject property.

This report is based on Pioneer's review of available historical and environmental records; visual inspections of the subject property and adjoining properties; and interviews with

available persons having knowledge of the property. Section 1.5 of this report, Findings/Conclusions is considered an Executive Summary and should be reviewed in conjunction with the entire report.

Pioneer declares that, to the best of our professional knowledge and belief, we meet the definition of Environmental Professional as defined in 312.10 of 40 CFR 312 and have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property. Pioneer has developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.

#### 1.7 REFERENCES

ASTM, 2005. Designation E 1527-05; Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process

ASTM, 2006. Designation E 1528-06; Standard Practice for Limited Environmental Due Diligence: Transaction Screen Process

Carter, R., 2011. *Environmental Site Assessment, St. Ignatius, Montana*. Report completed for Pioneer Technical Services, Missoula, Montana, 55 pp. Not published

Emergency Response Notification System, n.d., retrieved from <a href="https://cfpub.epa.gov/si/si">https://cfpub.epa.gov/si/si</a> public record report.cfm?Lab=&dirEntryId=2874

Federal Comprehensive Environmental Response Search, n.d., retrieved from <a href="https://www.epa.gov/enviro/sems-search">https://www.epa.gov/enviro/sems-search</a>

Federal Resource Conservation and Recovery Act, n.d., retrieved from https://www3.epa.gov/enviro/facts/rcrainfo/search.htmlFederal Superfund Site System, n.d., retrieved from https://www.epa.gov/superfund

LaFave et al., 2004. Montana Bureau of Mines and Geology; Montana Ground-Water Assessment Atlas 2; Ground-Water Resources of the Flathead Lake Area: Flathead, Lake, Missoula, and Saunders Counties, Montana

Montana Department of Environmental Quality Comprehensive Environmental Cleanup and Responsibility Act Priority, n.d., retrieved from <a href="http://deq.mt.gov/Land/statesuperfund/cecra">http://deq.mt.gov/Land/statesuperfund/cecra</a>

Montana Department of Environmental Quality Mine Waste Cleanup Bureau, n.d., retrieved from http://deq.mt.gov/Land/fedsuperfund

Montana Leaking Underground Storage Tank, n.d., retrieved from <a href="http://deq.mt.gov/Land/lust/lustsites">http://deq.mt.gov/Land/lust/lustsites</a>

Montana State and tribal Brownfields Sites, n.d., retrieved from <a href="http://deq.mt.gov/Land/brownfields/brownfieldssites">http://deq.mt.gov/Land/brownfields/brownfieldssites</a>

Montana State Equivalent Comprehensive Environmental Response Search, n.d., retrieved from <a href="http://environment.netronline.com/state/MT/cerclis/">http://environment.netronline.com/state/MT/cerclis/</a>

Montana State Equivalent National Priorities List, n.d., retrieved from <a href="http://environment.netronline.com/state/MT/npl/">http://environment.netronline.com/state/MT/npl/</a>

Montana State Landfill, n.d., retrieved from http://deq.mt.gov/Land/solidwaste

Montana State Library Cadastral System, n.d., retrieved from <a href="http://svc.mt.gov/msl/mtcadastral/">http://svc.mt.gov/msl/mtcadastral/</a>

Montana State Property Records Search Portal, n.d., retrieved from <a href="http://svc.mt.gov/msl/mtcadastral/">http://svc.mt.gov/msl/mtcadastral/</a>

Montana Underground Storage Tank, n.d., retrieved from <a href="http://deq.mt.gov/Land/ust/ustdownloads">http://deq.mt.gov/Land/ust/ustdownloads</a>

National Priorities List, n.d., retrieved from <a href="https://www.epa.gov/superfund/superfund-national-priorities-list-npl">https://www.epa.gov/superfund/superfund-national-priorities-list-npl</a>

Chapter 2: Hydrogeology Characteristics of Waste Management Area U, Hanford, Washington

#### 2.1 INTRODUCTION

This chapter is an excerpt from the Engineering Evaluation Report for Single-Shell Tank Waste Management Area U Groundwater Monitoring (Sulloway, et al., 2018). This chapter briefly describes the local geology and hydrogeology beneath the Waste Management Area U (WMA U) area (Figure 8). This information is summarized from the Groundwater Quality Assessment Plan for the Single-Shell Tank Waste Management Area U (PNNL-13612 and DOE/RL-2009-74, Rev. 1) and is intended to provide a brief overview of the current understanding of the site.

WMA U, which includes the single-shell tanks (SSTs) and ancillary equipment of the U Tank Farm, is located in the south-central portion of the 200 West Area, near U Plant (Figure 8). SSTs in WMA U were used for interim storage of highly radioactive waste (called "metal" waste) generated by nuclear fuel reprocessing using the bismuth phosphate process at B and T Plants. WMA U contains 16 underground SSTs constructed between 1943 and 1944. The WMA also contains ancillary equipment used to manage tank waste during operations, including six diversion boxes, the 271-UR control house, the 244-UR process vault, the 244-U double-contained receiver tank, waste transfer lines, pits, and junction boxes.

The tanks in WMA U began operations in 1946 and were in continual use until 1980, at which time they were removed from service. Most of the metal waste was subsequently removed from the tanks and recycled through U Plant to remove uranium. WMA U subsequently received fuel reprocessing waste from the Reduction Oxidation (REDOX) Plant and from other waste operations such as Plutonium Uranium Extraction Facility (PUREX). The tank farm was later interim stabilized (by removing pumpable liquids from the tanks) and isolation activities were performed (DOE/RL-91-52; PNNL-13282, Groundwater Quality Assessment for Waste Management Area U: First Determination).

# 2.2 STRATIGRAPHY

The local stratigraphy beneath WMA U consists of unconsolidated to semiconsolidated sediments overlying basalt bedrock of the Columbia River Basalt Group. The sedimentary units present (in descending sequence) are as follows:

- Sand and gravel backfill
- Sand and gravel of the Hanford formation
- Fine-grained Cold Creek unit
- Sand and gravel of the Ringold Unit E
- Fine-grained Ringold lower mud unit
- Sand and gravel of Ringold Unit A (which overlies the basalt)




Figure 8. Location Map for the Waste Management Area U

WMA U is underlain by approximately 150 m (490 ft) of suprabasalt sediment. The major sedimentary units underlying the WMA are the Ringold Formation and the Hanford formation (Figure 9). The Cold Creek unit occurs between the Ringold Formation and the Hanford formation. The Ringold Formation consists of Miocene-Pliocene fluvial and lacustrine elastic sediment deposited by the ancestral Columbia River system. The sediment rests unconformably on the Miocene-age Columbia River Basalt Group. Lindsey (1995), using a depositional environment approach, identified several facies within the Ringold Formation. Using facies associations, Lindsey divided the Ringold Formation into three informal members. The Ringold Formation underlying WMA U belongs entirely to the Member of Wooded Island, the lowest member of the formation. Lindsey divided the Member of Wooded Island into five gravel-dominated fluvial depositional units (A, B, C, D, and E), separated by widespread overbank, paleosol, and lacustrine deposits. The lower mud unit, a thick lacustrine deposit, separates gravel unit A from the overlying deposits.

The Cold Creek unit, which separates the Ringold Formation from the Hanford formation, is divided into two distinct sequences. The upper sequence of thinly laminated silts was identified as lacustrine deposits. Calcium carbonate-rich strata characterize the lower sequence. This lower interval consists of locally derived basaltic detritus, silt-rich eolian deposits, reworked Ringold material, and calcium carbonate-rich paleosols. The calcium carbonate occurs as thin (<2.5 cm) layers, nodules, and coatings on clasts.

The Hanford formation is an informal stratigraphic unit made up of uncemented gravel, sand, and silt deposited by the late Pleistocene Missoula glacial floods. The Hanford formation can be described in terms of three gradational facies: gravel dominated, sand dominated, and silt dominated. At WMA U the upper portion of the Hanford formation is gravel dominated and the lower portion is sand and silt dominated. At WMA U, the upper, gravel dominated unit is approximately 16 m (53 ft) thick, and the Hanford formation has a total thickness of approximately 35 m (115 ft).

## 2.3 HYDROGEOLOGY

Groundwater beneath WMA U occurs as an unconfined aquifer and deeper confined aquifers. The water table occurs in the Ringold Formation Member of Wooded Island (Figure 10). Depth to water range from 70.6 m (231 ft) to 74.9 m (246 ft). The uppermost confined aquifer occurs in Ringold unit A and is confined above by the lower mud unit and below by basalt. Deeper confined aquifers occur between the basalt flows.

The base of the unconfined aquifer is the fine-grained Ringold lower mud unit. The lower mud unit is at least partly confining and is continuous beneath WMA U (*Development of the Hanford South Geologic Framework Model Hanford Site*, ECF-Hanford-13-0029, Rev. 4) isolating the confined aquifers from potential releases from WMA U. The unconfined aquifer is approximately 70 m (230 ft) thick.




Figure 9. General Stratigraphy at the Hanford Site

A more detailed description of the geology of WMA U is provided in Subsurface Conditions

Description of the U Waste Management Area (RPP-15808) and Groundwater Quality

Assessment Plan for Single-Shell Tank Waste Management Area U (PNNL-13612). Revised

Hydrogeology for the Suprabasalt Aquifer System, 200 West Area and Vicinity, Hanford Site,

Washington (PNNL-13858) describes the hydrogeology of the entire 200 West Area and vicinity.

Water beneath the WMA U is found in the unsaturated vadose zone above the water table and in the saturated zone below the water table. Properties of groundwater in both regions are important in understanding how the WMA may impact groundwater quality.

The unsaturated sediments above the water table affect how waste solutions move through the soil, how much is retained in the sediment column, and how much waste eventually reaches the water table. The source of contamination for the WMA is liquid waste released to near surface or subsurface sediments. These liquids move through the sediment under unsaturated conditions and as a result, tend to spread laterally at changes in stratigraphy. Small volume leaks would tend to be retained in the vadose zone near the leak point. Larger leaks would be expected to move deeper in the soil, spreading laterally as the wetting front moves downward.

A major stratigraphic change is the top of the Cold Creek unit. This unit, located about 30 m (98.4 ft) below ground surface would slow the downward movement of water and divert it to the southwest, the direction the top of the unit is dipping beneath the WMA. Water from a waste release may reach the water table at a time, location, and concentration depending on its volume, depth of release, and diversion from downward movement at a stratigraphic change. Over time, wastewater released to the sediment column near ground surface will evaporate or be driven downward to the water table by new inputs of water to the sediment column from above. It is this downward movement of water in the vadose zone that carries waste contaminants to the water table. Water movement in the unsaturated zone is relatively slow compared to groundwater flow below the water table, delaying the observed impact of a near surface waste release on groundwater quality.

# 2.4 GROUNDWATER FLOW SYSTEM

Elements of the groundwater flow system beneath WMA U are described in the following subsections. These elements include the effects of historical anthropogenic discharges to ground in the 200 West Area, resulting changes in groundwater elevation and flow direction and velocity, and more recently, implementation of groundwater remediation using P&T systems that remove, treat, and replace water into the aquifer.




Figure 10. East to West Cross-Section for Waste Management Area U

# Hydrologic Conditions Prior to 200 West Pump and Treat Operations

Groundwater flow conditions at WMA U have varied greatly over the past several decades due to changing wastewater disposal in areas surrounding the WMA. Between 1950 and 1970, the groundwater flow direction beneath the WMA varied between southeast, east, and northeast, depending on effluent disposal volumes to the former 216-T-4 Pond to the north of the WMA and the former 216-U-10 Pond to the southwest (PNNL-16069, *Development of Historical Water Table Maps of the 200 West Area of the Hanford Site* [1950-1970]). During the 1980s, the flow direction changed from northeast to east in response to the decommissioning of the 216-U-10 Pond in 1985. In the late 1980s and early 1990s, nearby effluent discharges were occurring at the 216-Z-20 Crib to the west of the WMA and the 216-U-14 Ditch to the east (see Figure 11 for waste site locations). The effluent volume discharged to the 216-Z-20 Crib declined in 1992, and the flow direction beneath the WMA reversed to westerly because discharges to the 216-U-14 Ditch became dominant. Discharges to both sites had ceased by 1996, and the flow direction has been toward the east-northeast since that time.

# Hydrologic Conditions Due to Operation of the Pump and Treat Remedy

Water levels in the monitoring wells declined an average of 0.37 m/yr (1.21 ft/yr) from 2014 to 2016 (DOE/RL-2016-67, *Hanford Site Groundwater Monitoring Report for 2016*). The decline is due to the substantial reduction of wastewater discharges to the soil column in the mid-1990s and operation of the 200 West pump and treat (P&T).

The 2016 Hanford Site water table map shows groundwater flow direction to the east-northeast beneath the WMA (Figure 12). Groundwater flow is affected by the 200 West P&T remedy, which began operating in 2012. The system extracts and treats contaminated groundwater. One extraction well (299-W17-3) is located near the WMA approximately 150 m (490 ft) north-northeast. Drawdown around this well accounts for the increased gradient at WMA U. The extraction well is shown on the 2016 water table map (Figure 12). The hydraulic gradient beneath the WMA is estimated to be  $5.0 \times 10^{-3}$  m/m based on a trend surface analyses performed on four sets of water level measurements at WMA U during 2016. The average

groundwater 2016 flow rate of 0.18 m/d (0.58 ft/d) was consistent with the 2015 average rate of 0.19 m/d (0.62 ft/d) (DOE/RL-2016-67).

Baseline groundwater levels were evaluated in two dimensions by interpolating water-level data obtained during June 2012, at which time no groundwater remedy was operating. Figure 13 shows the 2012 water table map prior to the start of the P&T remedy. During this time, groundwater flow direction was to the east-northeast. The hydraulic gradient is estimated to be  $2.1 \times 10^{-3}$  m/m in 2012 with an average linear velocity of 0.018 to 0.20 m/day (0.05 to 0.7 ft/day) (SGW-55438, Hanford Site Groundwater Monitoring for 2012: Supporting Information).




Figure 11. Waste Site Locations Near Waste Management Area U




Figure 12. 2015 Water Table Map for the Waste Management Area U




Figure 13. Water Elevation Contours in June 2012 Prior to Startup of the 200 West P&T

#### 2.5 VADOSE ZONE

The vadose zone at WMA U is approximately 70.6 m (236 ft) to 74.9 m (246 ft) thick and consists of (from top to bottom) the Hanford formation, the Cold Creek Unit, and the Ringold Formation. The lower hydraulic conductivity of the Cold Creek Unit is likely to slow downward movement of moisture and contaminants because of the finer textured sediment and associated calcium carbonate cementation that results in a low hydraulic conductivity of the Cold Creek Unit. Although the Cold Creek Unit is clearly a restriction to vertical migration of water (and associated dissolved contaminants) beneath WMA U, it is not impermeable and contaminated water can eventually reach the underlying groundwater. This is indicated by the apparent presence of contaminants from WMA U in groundwater at the site.

The unsaturated sediments above the water table affect how waste solutions move through the soil, how much is retained in the sediment column, and how much contamination eventually reaches the water table. The source of contamination for the WMA is liquid waste released to near-surface or subsurface sediments. These liquids would be expected to move through the sediment under both saturated and unsaturated conditions, depending on the volume of liquid released. In addition to expected lateral distribution in relatively homogeneous portions of the formation, lateral spreading may occur at changes in soil texture and hydraulic conductivity. Small volume leaks would tend to be retained in the vadose zone near the leak point. Larger releases would be expected to move deeper in the soil, spreading laterally as the wetting front moves downward.

## 2.6 SOIL MOISTURE FACTORS

Tank leak/release events typically began with rapid discharge of some waste fluid volume into the subsurface from a point of release likely having a small spatial extent (on the order of inches to rarely feet). This discharge temporarily increases the moisture content of the unsaturated soil, particularly at the point of release. Typical release points may include poorly sealed openings in the tank structure, ruptured areas of steel tank liners nearby underlying concrete shell fractures and breaks in waste transfer lines. Free liquids in soil move downward generally by gravity and move laterally typically by the forces of soil capillarity. The initial rate

of liquid movement and the volume of soil that is eventually wetted by any particular release is a function of the volume of the leak, its duration, and the initial moisture content of the surrounding soil. The hydraulic conductivity of damp and/or wet soil is substantially higher than dry soil. Subsurface soil characterization at WMA U (PNNL-17163, *Characterization of Direct Push Vadose Zone Sediments from the 241-U Single-Shell Tank Farm*) indicated that much of the subsurface soil was relatively wet (i.e., wetter than the natural moisture content of soil in an arid environment).

Migration process at SST sites are anticipated to occur, for the most part, in partially saturated soils because leak/release volumes were not sufficient to fill the soil pore spaces for an appreciable length of time or very far from the point of entry. This condition is referred to as "unsaturated flow." In addition to vertical flow, lateral flow may occur under both saturated and unsaturated conditions due to the effects of capillary action and due to the effects of wetting front encountering zones of varying hydraulic conductivity. In formations such as those encountered in the Hanford Site, soil layers with different hydraulic properties tend to be layered horizontally by sediment deposition processes. Consequently, flow in the lateral direction could occur at numerous depth intervals within the vadose zone.

External sources of water or other liquid may drive the contamination further downward. Infiltration of water from precipitation and unintentional, manmade releases such as leaking water lines may move residual waste remaining in the soil downward to the groundwater. Another potential source of water was discharges to nearby wastewater disposal sites: the 216-Z-20 Crib and Z Ditches to the west, and the 216-U-14 Ditch to the east (RPP-23405, *Tank Farm Vadose Zone Contamination Volume Estimates*). These historical discharges likely created substantial areas of perched water atop the Cold Creek Unit; these perched units may have migrated laterally beneath WMA U, providing additional driving force for historical releases from the WMA. Historical observations of perched water during drilling wells in the vicinity of these waste sites, and others, indicates the possibility of historical perched water migration.

## 2.7 HYDROGEOLOGIC CONSIDERATIONS

Prior to startup of the 200 West P&T system in 2012, the groundwater flow direction under WMA U was east at a calculated rate (using the Darcy relationship) of 0.08 m/d (0.26 ft/d) (DOE/RL-2011-118, Hanford Site Groundwater Monitoring for 2011). In 2015, the groundwater flow direction beneath the WMA was generally east to northeast as a result of groundwater extraction and injection for the 200 West P&T with a calculated groundwater velocity of 0.04 to 0.50 m/d (0.15 to 1.6 ft/d) (DOE/RL-2016-09, Hanford Site Groundwater Monitoring Report for 2015).

Pump and treat operations are expected to continue in this region until 2037. After completion of active groundwater remediation and the 200 West P&T system is shut down, groundwater flow is anticipated to return to pre 200 West P&T startup conditions. The changing groundwater flow directions and gradients will be considered when evaluating the groundwater monitoring network.

# 2.8 GROUNDWATER CHEMISTRY

Under the current groundwater flow regime, contaminants reaching the groundwater from a release at WMA U would migrate as dissolved contamination plume(s) toward the east-northeast with the groundwater flow. The average groundwater flow rate for 2016 has been estimated at 0.18 m/d (0.59 ft/d). Section 6.4 in RPP-35485 (*Field Investigation Report for Waste Management Area U*) discusses the conceptual models of tank leak/release pathways to the groundwater at WMA U in more detail.

- The following contaminants are present in the aquifer at WMA U:
  - o Chromium
  - o Carbon tetrachloride
  - o Nitrate
  - o Technetium-99

WMA U is the apparent source of groundwater contamination limited to the downgradient (east) side of the tank farm (Chapter 6.0 in PNNL-13282, *Groundwater Quality Assessment for Waste Management Area U First Determination*). During 2016, chromium was detected in

several downgradient wells at concentrations from 4.49 to 34.2  $\mu$ g/L. The concentration in upgradient well 299-W18-40 was 6  $\mu$ g/L. Conditions related to corrosion of stainless steel well components can also result in detectable chromium in groundwater samples. Corrosion-related chromium, however, is typically accompanied by iron, nickel, manganese, and occasionally other metals at definable concentrations relative to the proportion of the metals in the steel alloy. This condition has not been confirmed at WMA U.

While dissolved chromium (generally present as the chromate hexavalent chromium ion) is highly mobile in the aquifer, it can migrate more slowly than the movement of moisture in the vadose zone beneath the tank farms, at least initially following release from a tank. This has been attributed to a reduction process where tank fluids dissolve divalent iron minerals in the sediment. The iron then reacts with the soluble hexavalent chromium, reducing it to trivalent chromium, which precipitates as an insoluble iron chromium hydroxide (Zachara et al., 2007). This reaction may explain the current low concentrations of chromium in the groundwater. In the aquifer, dissolved chromium migrates to the east-northeast at the calculated groundwater flow rate of 0.18 m/d (0.59 ft/d).

Concentrations of the nondangerous constituent nitrate are above 45 mg/L in all network wells, including the upgradient well. The upgradient nitrate source is treated water injected into wells formerly used for the 200-ZP-1 interim action P&T system. This injected water was treated for VOCs but still contained nitrate (DOE/RL-2011-118, Hanford Site Groundwater Monitoring Report for 2011). The concentration in upgradient well 299-W18-40 was 79.7 mg/L, and the trend has been increasing since this well was drilled in 2001. Because nitrate in some downgradient wells are higher than the upgradient well, it is likely that WMA U is also a source of nitrate to the groundwater.

WMA U is a source of technetium-99 groundwater contamination (PNNL-13282). Although technetium-99 is not regulated under RCRA, it is mentioned in this discussion because the pattern of concentration changes of technetium-99 in wells downgradient of WMA U strongly parallels the behavior of nitrate in those wells. Concentrations in many downgradient wells are stable or slowly increasing, with the exception of well 299-W19-45 in which concentrations

have increased substantially since 2011. During 2016, concentrations in this well increased to 8,730 pCi/L from the 2015 maximum of 6,950 pCi/L. During 2016, technetium-99 also exceeded the 900 pCi/L cleanup level for the 200-UP-1 OU in wells 299-W19-12, 299-W19-42, 299-W19-47, and 299-W18-260, with a maximum of 1,720 pCi/L in well 299-W18-260. The groundwater contamination at WMA U is believed to result from multiple sources in the WMA (Table 4-2 in HNF-EP-0182, Rev. 353, 2017, *Waste Tank Summary Report for Month Ending May 31, 2017*). The contamination is within the 200 West P&T capture zone.

## 2.9 SUMMARY OF VERTICAL DISTRIBUTION

Dangerous waste constituents specific to release from WMA U are not present in groundwater at depth based on historical monitoring. Evaluation of vertical distribution data is limited to the location of WMA U within the context of regional plumes present in 200-UP-1 OU including contaminant plumes originating from WMA U. Available vertical distribution data are limited to one well (299-W18-260) completed northeast of WMA U and samples collected during drilling. See Figure 12 for well location in relation to WMA U. This well was installed in September and October, 2014. The lack of observations and measurements introduces substantial uncertainty in interpreting correlation between individual well data and the WMA U operations.

Evaluated constituents were limited to available nonradiological vertical data associated with surrounding wells. Vertical profile samples were analyzed for carbon tetrachloride and nitrate, representing wide spread contaminants in 200-UP-1 OU, and present near WMA U. During drilling of well 299-W18-260, groundwater samples were collected from the borehole at selected depths and analyzed by field and/or laboratory methods. Laboratory data were selected where both field and laboratory data were available for the vertical contaminant distribution plot. See Figure 14 for the observed vertical distribution of identified contaminants.

Well 299-W18-260 exhibits few measurements of vertical characterization data, consisting of carbon tetrachloride and nitrate at five sample depths collected at elevations between 2.7 m (8.9 ft) and 26.3 m (86.3 ft) below the 2017 water table. Based on vertical characterization data, contaminants are present within the upper sections of the unconfined aquifer; consistent with the presence of multiple sources and extents of regional plumes. Well 299-W18-260 exhibits an

increase in carbon tetrachloride and nitrate concentrations beginning about 2 m (6.6 ft) and 8 m (26.2 ft), extending to 20 m (65.6 ft) and 25 m (82.0 ft), respectively, below the 2017 water table.

In summary, the WMA U is located within the regional 200 West Area plumes and within the local-scale plumes. It is additionally impacted by the current, local 200-UP-1 P&T and 200 West P&T well network operations. Based on the limited data available, the vertical distribution of plume concentrations do not appear to penetrate the entire depth of the aquifer. Available data for the well are not sufficiently representative to evaluate vertical plume migration from a release from WMA U.




Figure 14. Vertical Contamination Distribution in Well 299-W18-260

#### 2.10 REFERENCES

Brown, C. F., et al., 2007. *Characterization of Direct Push Vadose Zone Sediments from the 241-U Single-Shell Tank Farm* (PNNL-17163). Report prepared by Pacific Northwest National Laboratory for the Department of Energy, Richland Office:

https://pdw.hanford.gov/arpir/index.cfm/viewDoc?accession=0911240534

Department of Energy, Richland Office, 1992. *Groundwater Quality Assessment for Waste Management Area U* (DOE/RL-91-52). Report prepared by CH2M Hill Plateau Remediation Company for the Department of Energy, Richland Office:

https://pdw.hanford.gov/arpir/index.cfm/viewDoc?accession=D196110688

Department of Energy, Richland Office, 2008. *Tank Farm Vadose Zone Contamination Volume Estimates* (RPP-23405, Rev. 3). Report prepared by CH2M Hill Plateau Remediation Company for the Department of Energy, Richland Office:

https://pdw.hanford.gov/arpir/index.cfm/viewDoc?accession=0075590H

Department of Energy, Richland Office, 2009. *Interim Status Groundwater Quality Assessment Plan for the Single Shell Tank Waste Management Area U* (DOE/RL-2009-74, Rev. 1). Report prepared by CH2M Hill Plateau Remediation Company for the Department of Energy, Richland Office: https://pdw.hanford.gov/arpir/index.cfm/viewDoc?accession=0091457

Department of Energy, Richland Office, 2009. *Subsurface Conditions Description of the U Waste Management Area* (RPP-15808). Report prepared by CH2M Hill Plateau Remediation Company for the Department of Energy, Richland Office:

https://pdw.hanford.gov/arpir/index.cfm/viewDoc?accession=0911240299

Department of Energy, Richland Office, 2012. *Hanford Site Groundwater Monitoring Report for 2011* (DOE/RL-2011-118). Report prepared by CH2M Hill Plateau Remediation Company for the Department of Energy, Richland Office:

https://pdw.hanford.gov/arpir/index.cfm/viewDoc?accession=0091795

Department of Energy, Richland Office, 2013. *Hanford Site Groundwater Monitoring for 2012: Supporting Information* (SGW-55438). Report prepared by CH2M Hill Plateau Remediation Company for the Department of Energy, Richland Office:

https://pdw.hanford.gov/arpir/index.cfm/viewDoc?accession=0087999

Department of Energy, Richland Office, 2016. *Hanford Site Groundwater Monitoring Report for 2015* (DOE/RL-2016-09). Report prepared by CH2M Hill Plateau Remediation Company for the Department of Energy, Richland Office:

https://pdw.hanford.gov/arpir/index.cfm/viewDoc?accession=0075314H

Department of Energy, Richland Office, 2017. *Hanford Site Groundwater Monitoring Report for 2016* (DOE/RL-2016-67). Report prepared by CH2M Hill Plateau Remediation Company for the

Department of Energy, Richland Office:

https://pdw.hanford.gov/arpir/index.cfm/viewDoc?accession=0068229H

Department of Energy, Richland Office, 2017. Waste Tank Summary Report for Month Ending May 31, 2017 (HNF-EP-0182, Rev. 353). Report prepared by Washington River Protection Solutions for the Department of Energy, Richland Office:

https://pdw.hanford.gov/arpir/index.cfm/viewDoc?accession=0069268H

Hammond, T.B., 2016. *Development of the Hanford South Geologic Framework Model Hanford Site* (ECF-Hanford-13-0029, Rev. 4). Report prepared by Intera Inc. for the Department of Energy, Richland Office:

https://pdw.hanford.gov/arpir/index.cfm/viewDoc?accession=0072357H

Hodges, F.N. and Chou, C.J., 2003. *Groundwater Quality Assessment for Waste Management Area U: First Determination* (PNNL-13282). Report prepared by Pacific Northwest National Laboratory for the Department of Energy, Richland Office:

https://pdw.hanford.gov/arpir/index.cfm/viewDoc?accession=D2760779

Kinney, T. M., and McDonald, J. P., 2006. *Development of Historical Water Table Maps of the 200 West Area of the Hanford Site (1950-1970)* (PNNL-16069). Report prepared by Pacific Northwest National Laboratory for the Department of Energy, Richland Office: <a href="https://www.pnnl.gov/main/publications/external/technical reports/PNNL-16069.pdf">https://www.pnnl.gov/main/publications/external/technical reports/PNNL-16069.pdf</a>

Lindsey, K.A., 1995. *Miocene- to Pliocene-Aged Suprabasalt Sediments of the Hanford Site, South-Central Washington*. BHI-00184, Bechtel Hanford, Inc., Richland, Washington

Smith, R.M., et al., 2001. *Groundwater Quality Assessment Plan for Single-Shell Tank Waste Management Area U* (PNNL-13612). Report prepared by Pacific Northwest National Laboratory for the Department of Energy, Richland Office:

https://pdw.hanford.gov/arpir/index.cfm/viewDoc?accession=D2760703

Sulloway, H., Carter, R. M., and Ni, J. 2018. *Engineering Evaluation Report for Single-Shell Tank Waste Management Area U Groundwater Monitoring*. Report prepared by CH2MHill Plateau Remediation Company for the Department of Energy, Richland Office, 219 pp. <a href="https://pdw.hanford.gov/arpir/index.cfm/viewDoc?accession=0064667H">https://pdw.hanford.gov/arpir/index.cfm/viewDoc?accession=0064667H</a>

Williams, B.A., et al., 2002. Revised Hydrogeology for the Suprabasalt Aquifer System, 200 West Area and Vicinity, Hanford Site, Washington (PNNL-13858). Report prepared by Pacific Northwest National Laboratory for the Department of Energy, Richland Office: https://www.pnnl.gov/main/publications/external/technical\_reports/PNNL-13858.pdf

Zachara, J. M., Serne, J., Freshley, M., Mann, F., Anderson, F., Wood, M., Jones, T, and Myers, D. 2007. Geochemical Processes Controlling Migration of Tank Wastes in Hanford's Vadose Zone. Vadose Zone J. 6:985-1003. doi:10.2136/vzj2006.0180

Chapter 3: Hydrogeologic Factors of a Chromium Plume at Hanford, Washington

#### 3.1 INTRODUCTION

This chapter consists of a section of a larger report written by CHPRC, specifically by the S&GRP (Rohay and Carter, 2018). The chapter presented here is verbatim with minor edits for clarity and reviews the approach of the southeast chromium plume remedial design investigation and the sampling and analysis plan (SAP) requirements. Historically, the extent of the southeast chromium plume was not sufficiently defined to support remedy implementation, particularly on the south side of the plume. Characterization activities to refine the vertical and horizontal extent of the plume to focus and optimize the remedial design were required by the 200-UP-1 OU Remedial Design/Remedial Action Work Plan (RD/RAWP) (DOE/RL-2013-07). In accordance with the RD/RAWP, the data quality objective process was used to define the final number, location, and type of wells, as well as the measurement frequency. Consideration was given to sampling groundwater over the entire thickness of the aquifer to understand the vertical distribution of concentrations and to select the appropriate screen interval(s). The flexibility of completing the wells for dual-use (i.e., monitoring wells and extraction or injection wells) was also considered. The results of the DQO process were documented in the 200-UP-1 OU SAP (DOE/RL-2014-27, Rev. 2, Sampling and Analysis Plan for Remediation Wells in the 200-UP-1 Operable Unit).

# 3.1 SAMPLING AND ANALYSIS PLAN REQUIREMENTS

The SAP for drilling of the southeast chromium plume wells defined sampling and analytical requirements for the remedial design investigation (DOE/RL-2014-27, Rev. 2). Characterization data needed for the investigation included the vertical profile and lateral extent of chromium contamination in groundwater, aquifer particle size distribution over the well screen interval, and information to evaluate the fate and transport of contaminants. The number and location of samples, sampling procedures, and analyses were specified in the field sampling plan (DOE/RL-2014-27, Rev. 2).

Initially, six characterization wells were planned to further define the nature and extent of the southeast chromium plume to support remedial design. These six wells were located based on the extent of the 2015 plume, shown on Figure 15, which was the latest interpretation at the

start of the drilling program. Chromium concentrations at the two northern wells (699-31-68 and 699-32-64) were consistent with the 2015 plume, but the relatively high concentrations in the three southern wells (699-29-66, 699-30-63, and 699-30-57) indicated that the plume above the 48 µg/L cleanup level extended farther south. The U. S. Department of Energy, Richland, Washington Operations Office (DOE-RL) and the U.S. EPA representatives met on January 19, 2017 to review the findings from the first six wells and agreed to install and sample four additional characterization wells in 2017. These four wells were located to investigate the eastern (699-31-50), southeastern (699-29-55), southwestern (699-27-68) and western (699-30-70) extent of the plume. DOE-RL and EPA also agreed to collect four quarters of groundwater samples from each of the initial six wells to evaluate the groundwater monitoring data for temporary reducing conditions affecting chromium concentrations. Results of the four quarters of monitoring were submitted to DOE-RL in April 2018.

In well 699-30-70, chromium concentrations during drilling were relatively high (average of 91  $\mu$ g/L), indicating that the plume extended farther to the west. DOE-RL and EPA met on July 20, 2017 and agreed to drill an eleventh well (699-30-73) to define the western extent of the plume closest to the 216-S-10 complex source. Concurrence was reached that 11 wells would be sufficient to define the nature and extent of the southeast chromium plume for remedial implementation, support completion of the Draft A remedial design investigation report, and satisfy the remedial design investigation requirement of Tri-Party Agreement (TPA) milestone M-16-193 for the southeast chromium plume.




Figure 15. Locations of the Eleven Southeast Chromium Plume Remedial Design Investigation Wells

Table 1 summarizes the samples collected during drilling of the 11 southeast chromium characterization wells and compares the planned depths (from Table 3-1 in the SAP; DOE/RL-2014-27, Rev. 2) to the actual depths.

# 3.2 CONTAMINANTS OF CONCERN

Chromium, measured as total chromium and hexavalent chromium, was the target contaminant of concern (COCs) for this remedial design investigation. Groundwater samples were also analyzed for tritium to determine whether the southeast chromium plume was commingled with the nearby tritium plume. Samples were analyzed for manganese, dissolved oxygen, and oxidation reduction potential as indicators of reducing conditions. Analytes for sampling are identified in Table 3-1 of DOE/RL-2014-27, Rev. 2.

Table 1. 200-UP-1 Operable Unit Southeast Chromium Plume Depth Discrete Samples

Well Name (ID)/Type	Sample Matrix	Planned Sample Depth		Actual Sample Depth	
		Below Water Table (ft)	Borehole Depth (ft)	Below Water Table (ft)	Borehole Depth (ft)
699-27-68 (C9632)/ Monitoring	Water	10	231	18.3	235.2
		30	251	37.6	254.6
		50	271	57.2	274.1
	(depth discrete)	70	291	79	296
	discrete	90	311	98.1	315
		110	331	118.1	335
Wiemitering	Saturate	10	231	17.9-20.2	234.9-237.2
	d Soil (split spoon)	50	271	58.0-58.5	275.0-275.5
		90	311	98.5-99.0	315.5-316.5
		10	299	14.5	300.9
	Water (depth discrete)	30	319	34.5	320.9
		50	339	64.4	350.8
699-29-55 (C9634)/ Monitoring		70	359	84.5	370.9
		90	379	104.5	390.9
		_		124.5ª	410.9
	Saturate d Soil (split spoon)	10	299	9.5-10.0	295.5-296.0
		50	339	54.8-57.3	340.8-343.3
		90	379	104.9-106.9	390.9-392.9
699-29-66 (C9413)/ Monitoring	Water (depth discrete)	20	264	23.7	274
		90	334	83.2	334.2
		160	404	152	403
		_		240.9ª	491.1
	Saturate d Soil	20	264	24.6-27.1	274.1-276.6
		90	334	84.4-86.4	333.9-335.9

	(split spoon)	160	404	245.8-247.8	495.3-497.3
699-30-57	Water	20	307	31.9	317.2
	(depth	85	372	84.7	370.1
	discrete)	150 <sup>b</sup>	437	_	
(C9417)/	Saturate	20	307	17.6-20.1	306.5-309.0
Monitoring	d Soil	85	372	83.5-86.0	372.4-374.9
	(split spoon)	150 <sup>b</sup>	437	_	
		20	287	23.3	295.5
699-30-63	Matau	40	307	43.6	315.9
	Water (depth	65	332	63.3	335.6
	discrete)	90	357	83.4	355.7
(C9602)/	discrete;	110	377	103.2	375.5
Dual-Use		_		123.1 <sup>a</sup>	395.4
	Saturate	20	287	17.6-20.1	293.1-295.6
	d Soil	65	332	60.6-62.9	336.1-338.4
	(split spoon)	110	377	98.8-101.8	374.3-377.3
		10	226	15.1	235.5
		30	246	35	255.4
		50	266	55.1	275.4
	Water	70	286	75.1	295.4
699-30-70	(depth discrete)	90	306	94.9	315.2
(C9635)/	uiscrete)	110	326	114.9	335.2
Monitoring		130	346	134.1	354.4
Monteoning		150	366	154.1	374.4
	Saturate	10	226	16.1-18.5	236.1-238.1
	d Soil	70	286	75.7-78.1	395.7-298.1
	(split spoon)	130	346	134.1-135.5	354.1-355.5
		10	230	10.7	240.3
		30	250	30.6	260.3
		50	270	50.3	280
	Water	70	290	70.6	300.3
699-30-73	(depth	90	310	90.3	320
	discrete)	110	330	110.6	340.2
(C9636)/		130	350	130.4	360
Monitoring		150	370	150.5	380.2
		170 <sup>b</sup>	390	_	
	Saturate	10	230	10.9-11.4	240.9-241.4
	d Soil	70	290	71.3-71.8	301.3-301.8
	(split spoon)	130	350	130.2-130.7	360.2-360.7
		10	317	16.7	325
699-31-50 (C9737)/ Monitoring		30	337	35.2	345.1
	Water	50	357	56.4	366.2
	(depth	70	377	75.2	384.8
	discrete)	90	397	96.2	406
	l L	110	417	115.7	425.5
		_		135.2ª	444.9
	Saturate	10	317	16.0-17.5	325.0-326.5
	d Soil	50	357	54.7-57.2	363.7-366.2
	(split	90	397	95.0-97.0	404.0-406.0
	spoon)	_		115.0-116.5ª	424.0-425.5

699-31-68 (C9416)/	Water	20	283	40.3	304.5
	(depth	80	242	80.2	344.3
	discrete)	140	403	150.4	414.5
	Saturate	20	283	37.8-39.8	304.5-306.5
Monitoring	d Soil (split spoon)	80	242	77.6-79.6	344.3-346.3
		140	403	147.8-149.8	414.5-416.5
		20	326	31	336.5
	Water (depth discrete)	35	341	50.3	355.8
		55	361	71.2	376.8
699-32-59		75	381	80.9	386.5
(C9603)/		90 <sup>b</sup>	396	_	
Dual-Use	Saturate	20	326	26.6-29.1	335.5-338.0
	d Soil	55	361	49.7-51.7	358.6-360.6
	(split spoon)	90	396	79.2-81.7	385.2-387.7
		20	296	33.9	316
	Water	40	316	43.9	326
	(depth	60	336	62.7	344.7
699-32-64	discrete)	80	356	83.9	366
(C9601)/		100	376	104.1	386.1
Dual-Use	Saturate	20	296	22.8-25.7	307.7-310.6
	d Soil	60	336	60.9-63.7	345.8-348.6
	(split spoon)	100	376	99.5-101.7	384.4-386.6

a. Drill depth to the Ringold Lower Mud greater than estimated, additional sample required.

bgs = below ground surface

ID = identification

# 3.3 CHARACTERIZATION WELLS

The 11 southeast chromium plume wells were drilled between March 2016 and October 2017. The wells were drilled using air rotary technology to maintain oxygenated conditions, thus alleviating the reducing effects in the subsurface in accordance with the descriptions of work for drilling:

- SGW-59416, Description of Work for the Installation of Three Monitoring Wells in the 200-UP-1 Groundwater Operable Unit, FY16
- SGW-60084, Description of Work for the Installation of Three Multipurpose Wells in the 200-UP-1 Groundwater Operable Unit, FY2017
- SGW-60568, Description of Work for the Installation of Four Monitoring Wells Near the
   Southeastern Portion of the 200-UP-1 Operable Unit, FY 2017

b. Drill depth to the Ringold Lower Mud less than estimated, final estimated sample depth not reached.

Three of the original 6 wells were planned and constructed as dual-use wells (699-32-59, 699-30-63, and 699-32-64) and will initially be used for groundwater monitoring but could later be used for groundwater extraction or injection. The other 8 wells were planned and constructed as groundwater monitoring wells. Depth-discrete samples of saturated sediment and groundwater were collected in accordance with the SAP.

## 3.4 GROUNDWATER SAMPLES

Depth-discrete groundwater samples were collected during drilling of the 11 characterization wells to determine the vertical profile of chromium contamination. Groundwater samples were also collected following well development and during subsequent quarterly monitoring. Nearby existing groundwater wells were sampled to supplement the data from the new wells.

Groundwater samples were analyzed for total chromium and hexavalent chromium. Filtered total chromium concentrations are considered equivalent to hexavalent chromium concentrations, although there can be differences caused by normal analytical variability or sample turbidity. Filtered total and hexavalent chromium concentrations can be affected by temporary reducing conditions caused by the drilling process. Temporary chemically-reducing conditions have been documented when drilling at Hanford. The conditions are generally caused by the drilling activity breaking pieces of basalt, or other iron-bearing rock species, and exposing reduced iron in the fractured surfaces. The exposed reduced iron in rock surfaces can be readily oxidized by dissolved oxygen in the groundwater; this can temporarily reduce, or deplete, the oxygen content in the water, resulting in a temporary reducing condition. These reducing conditions can temporarily affect the oxidation state of other elements, including chromium and manganese. The reducing conditions can cause hexavalent chromium to reduce to trivalent chromium, which is less soluble and can cause concentrations observed during drilling to be artificially low. It can take up to a year after a well is drilled before the aquifer fully recovers and representative samples can be collected (DOE/RL-2011-118, Hanford Site Groundwater Monitoring Report for 2011), depending on the drilling method and the nature of the geological material encountered. Samples for manganese were collected because manganese is sensitive to reduction-oxidation conditions and was used as an indicator that

samples are representative of the oxidizing conditions normal to the Hanford aquifer (Section E.5.2, Appendix E of DOE/RL-2011-118).

## 3.5 VERTICAL PROFILE SAMPLING

Depth-discrete groundwater samples were generally collected from the upper, middle, and lower part of the aquifer for the first 3 wells drilled (699-29-66, 699-30-57, and 699-31-68), and every 6.1 m (20 ft) below the water table for the remaining 8 wells, to determine the vertical profile of chromium contamination in the unconfined aquifer. The first sample was typically collected 1.5 to 3.1 m (5 to 10 ft) below the targeted depth for the first water sample (Table 1) so that the well would produce enough water for sampling. All depth-discrete sample results are discussed in another section of the original report (DOE/RL-2017-60, Remedial Design Investigation Report for the 200-UP-1 Operable Unit Southeast Chromium Plume).

The samples were collected using a 3/4-horsepower temporary submersible pump. When possible, the boreholes were purged until dissolved oxygen stabilized at or above 7,000  $\mu$ g/L and oxidation-reduction potential was at least 200 mV (DOE/RL-2014-27, Rev. 2).

The sample depths for each well are listed in Table 1. An additional water sample was collected at wells 699-29-55, 699-29-66, 699-30-63, and 699-31-50 because the depth to the Ringold lower mud was greater than estimated. One less water sample was collected at wells 699-30-57, 699-30-73, and 699-32-59 because the depth of the Ringold lower mud was less than estimated.

## 3.6 GROUNDWATER DATA

Routine quarterly sampling of the first 6 new wells were used to evaluate temporal variability of filtered total chromium and hexavalent chromium. Quarterly samples are being collected from the last 5 new wells, but a year has not elapsed since drilling to allow the aquifer to recover from potential reducing effects of drilling. Groundwater results are discussed in another section of the original report (DOE/RL-2017-60).

# Groundwater Data from Existing Wells

Routine annual sampling of existing groundwater monitoring wells for total chromium and hexavalent chromium was conducted in 2017 based on the higher than anticipated chromium sample results in four of the initial six wells.

In addition, a Tri-Party Agreement Change Notice, TPA-CN-0802, identified five older wells near the south and east perimeter of the southeast chromium plume for inclusion in the monitoring well network.

## 3.7 SAMPLING DURING WELL DEVELOPMENT

Final well development for each of the eleven new southeast chromium plume wells was conducted at the completion of well development activities. Details regarding well development are available in the three borehole summary reports (Table 2-2 in SGW-60463, Borehole Summary Report for the Installation of Three Monitoring Wells in the 200-UP-1 Groundwater Operable Unit, Fiscal Year 2016; Table 2 in SGW-60727, Borehole Summary Report for Installation of Three Multipurpose Wells in the 200-UP-1 Groundwater Operable Unit, FY 2017). Well development was performed at one or more intervals. Each interval was pumped until water was less than five nephelometric turbidity units (NTU) and additional water quality parameters (conductivity, dissolved oxygen, pH, and temperature) had stabilized. Groundwater samples were collected following completion of well development. Results from the groundwater monitoring are discussed in another section of the original report (DOE/RL-2017-60).

No pumping tests or pumping test sampling were conducted during the installation of the eleven southeast chromium plume wells.

# Soil Samples

Saturated soil and groundwater samples were collected and sent to Pacific Northwest National Laboratory (PNNL) for research to support the Deep Vadose Zone Applied Field Research Initiative scientific investigations of controlling processes for contaminant behavior (DOE/RL-2014-27, Rev. 2). Three split-spoon soil samples were collected within the unconfined aquifer at

10 of the new wells and two samples were collected at well 699-30-57. Three to eight depth-discrete groundwater samples were collected at 10 of the new wells, no samples were collected from well 699-30-73 (Table 1).

The saturated soil samples were collected for PNNL using split-spoon samplers at the borehole to characterize the geochemistry of the sediment and associated pore water. Split-spoon samples were collected at the upper, middle, and lower portions of the unconfined aquifer, starting between 3 to 6.1 m (10 to 20 ft) below the water table. The 10.2-cm (4-in.) diameter sampler contained four 15.2-cm (6-in.) long liners. These liners were wrapped in plastic to preserve water content and transported to PNNL.

Chromium transport may be impacted by interaction with calcite or reductive processes. A single split-spoon sample from one well, 699-30-63, downgradient of the chromium source was selected for assessment of the presence and extent of these processes. The sample was analyzed using analytical methods (e.g., water, acid, and sequential extractions). Additional analyses were not performed because the initial laboratory results indicated that natural attenuation processes other than dispersion were not occurring (i.e., chromium was not found to be present in multiple phases at concentrations high enough to enable effective measurement of leaching characteristics) (DOE/RL-2014-27, Rev. 2). The results of the assessment are summarized in another section of the original report (DOE/RL-2017-60).

# 3.8 REFERENCES

Department of Energy, Richland Office, 2012. *Hanford Site Groundwater Monitoring Report for 2011* (DOE/RL-2011-118). Report prepared by CH2M Hill Plateau Remediation Company for the Department of Energy, Richland Office:

https://pdw.hanford.gov/arpir/index.cfm/viewDoc?accession=0091795

Department of Energy, Richland Office, 2013. 200-UP-1 Operable Unit Remedial Design/Remedial Action Work Plan (DOE/RL-2013-07). Report prepared by CH2M Hill Plateau Remediation Company for the Department of Energy, Richland Office: https://pdw.hanford.gov/arpir/index.cfm/viewDoc?accession=0087671

Department of Energy, Richland Office, 2017. *Borehole Summary Report for the Installation of Three Monitoring Wells in the 200-UP-1 Groundwater Operable Unit, Fiscal Year 2016* (SGW-60463). Report prepared by CH2M Hill Plateau Remediation Company for the Department of Energy, Richland Office:

https://pdw.hanford.gov/arpir/index.cfm/viewDoc?accession=0065665H

Department of Energy, Richland Office, 2017. *Borehole Summary Report for Installation of Three Multipurpose Wells in the 200-UP-1 Groundwater Operable Unit, FY 2017* (SGW-60727). Report prepared by CH2M Hill Plateau Remediation Company for the Department of Energy, Richland Office: https://pdw.hanford.gov/arpir/index.cfm/viewDoc?accession=0065663H

Department of Energy, Richland Office, 2017. *Sampling and Analysis Plan for Remediation Wells in the 200-UP-1 Operable Unit* (DOE/RL-2014-27, Rev. 2). Report prepared by CH2M Hill Plateau Remediation Company for the Department of Energy, Richland Office: https://pdw.hanford.gov/arpir/index.cfm/viewDoc?accession=0071352H

Department of Energy, Richland Office, 2018. *Remedial Design Investigation Report for the 200-UP-1 Operable Unit Southeast Chromium Plume* (DOE/RL-2017-60). Report prepared by CH2M Hill Plateau Remediation Company for the Department of Energy, Richland Office: <a href="https://pdw.hanford.gov/arpir/index.cfm/viewDoc?accession=0064659H">https://pdw.hanford.gov/arpir/index.cfm/viewDoc?accession=0064659H</a>

Rohay, V. and Carter, R. M. 2018. Remedial Design Investigation Report for the 200-UP-1 Operable Unit Southeast Chromium Plume, Draft A. Report prepared by CH2M Hill Plateau Remediation Company for the Department of Energy, Richland Office. 157 pp. https://pdw.hanford.gov/arpir/index.cfm/viewDoc?accession=0064659H

# Chapter 4: Epilogue – Lessons Learned and Future Plans

This portfolio paper showcases my efforts on environmental remediation and how people can respond to environmental issues such as hazardous waste disposal. This paper also shows the development of an environmental scientist/hydrogeologist and can also be used as a template for any environmental professional dealing with most community remediation sites. The portfolio includes research of the study areas, site reconnaissance, historical data research, interviews with owners and professionals, analytical analysis, quality assurance and quality control, and groundwater data interpretation.

The collection and interpretation of the data will hopefully provide a baseline to assist communities with concerns about potential impacts to the quality of their groundwater. Environmental site assessments and waste site remediation are continual concerns for the U.S. Environmental Protection Agency. As ongoing research further clarifies connections between a healthy environment and chronic health conditions, local site assessments and waste clean-up will become even more critical. The site assessment at St. Ignatius was a springboard for me as it peaked my interest and involvement of environmental concerns in waste disposal and site remediation. This project was my first experience utilizing regulatory framework to assess the impact or potential impact to the environment. Throughout this journey, I learned many lessons from mentors I worked with, as well as gained deeper insight into what environmental assessments means and how to facilitate its process.

Hanford groundwater contamination is a continual concern for the Tri-Cities, Washington region. As the next contract to clean up the Hanford site is coming due, continued research for clean drinking water is necessary. My plans are to continue to learn and grow within the scope of this clean-up effort. I plan on being a part of groundwater remediation projects and ongoing research for the foreseeable future and the rest of my career. Using my education as a backdrop, the position I currently fill has allowed me to advance my understanding of hydrogeology, geology, chemistry, scientific writing, and regulatory requirements.

Looking back at the site reconnaissance and data research for the St. Ignatius project, time management and thoroughness of the regulatory guidelines were the two most obvious obstacles. The work at Hanford is ongoing and will continue to be a source of learning. Knowing

and better understanding the chemical processes which are used during plutonium production is important since it helps determine the chemical constituents that have made their way to groundwater. This will take some time and a concerted effort on my part, as such, working with mentors and continually being immersed with site projects will give a framework for continual education. Learning the federal and state regulations is an important criteria for success, which will be a continual process. Waste site remediation is a critical step in returning the environment to its natural state and to provide clean drinking water for future generations.